


Human factors considerations for aviation safety



Robert Sumwalt



NTSB



NTSB

Thomson, GA

February 20, 2013



Accident aircraft prior to N-number change to N777VG.



NTSB



NTSB

Probable Cause

“The pilot's failure to follow airplane flight manual procedures for an antiskid failure in flight and his failure to immediately retract the lift dump after he elected to attempt a go-around on the runway.”

“Contributing to the accident were the pilot's lack of systems knowledge and his fatigue due to acute sleep loss and his ineffective use of time between flights to obtain sleep.”



Pilot activities

Night before trip		
	Went to bed	2100
Day of trip		
	Woke up	0200
	Departed home	0230
	Arrived airport	0330
	Departed for Nashville	0406
	Arrived Nashville	0459*
	Lunch	1500 – 1630*
	Passengers arrived	1918*
	Takeoff Nashville	1927*
	Crash at Thomson, GA	2005

* Times converted to EST



NTSB

Pilot activities

Night before trip		
	Went to bed	2100
	5 hours	
Day of trip		
	Woke up	0200
	Departed home	0230
	Arrived airport	0330
	Departed for Nashville	0406
	Arrived Nashville	0459*
	Lunch 14 hours	1500 – 1630*
	Passengers arrived	1918*
	Takeoff Nashville	1927*
	Crash at Thomson, GA	2005

* Times converted to EST



NTSB

Time	Cell phone activity
0808	Phone call - outgoing
0813	Phone call - outgoing
0902	Phone call - outgoing
1002	Text message - outgoing
1005	Text message - outgoing
1016	Text message - outgoing
1121	Text message - outgoing
1138	Phone call - outgoing
1234	Phone call - outgoing
1251	Phone call - outgoing
1300	Phone call - outgoing
1315	Phone call - outgoing
1317	Phone call - outgoing
1324	Phone call - outgoing
1330	Phone call - outgoing
1332	Phone call - outgoing
1404	Text message - outgoing
1432	Phone call - outgoing
1501	Phone call - outgoing
1503	Phone call - outgoing
1642	Phone call - outgoing

1 Incoming call

2 Incoming calls

2 Incoming calls

2 Incoming calls

2 Incoming calls

1 Incoming call

1 Incoming call




**National
Transportation
Safety Board**

Loss of Control Eurocopter AS350

Las Vegas, Nevada
December 7, 2011



Sequence of Events



Fuselage
and engine




Maintenance Performed day prior to accident

- 100-hour inspection
- Replacement of the following:
 - Engine
 - Fore/aft and tail rotor servos



View of Helicopter Components





Input rod and
fore/aft servo

Main rotor assembly

Cockpit and cabin




NTSB




Hardware

Input rod hardware




Hardware installed



NTSB

Input Rod and Servo



Fore/Aft Servo Installation

- Fore/aft servo installation procedures:
 - Assess hardware
 - Connect servo to input rod
 - Torque nut
 - Install split pin
- Inspect installation



Self-Locking Nut

Acceptable Nut



Degraded Nut



Hardware Reuse

- Post accident inspection of 13 Sundance helicopters - half of nuts did not meet below requirements

Manufacturer's guidance: "If a nut can be easily tightened, it is to be discarded"

FAA guidance: "DO NOT reuse a fiber or nylon lock nut if the nut cannot meet the minimum prevailing torque values"



NTSB Finding

- The fore/aft servo bolt most likely disengaged because:
 - the split pin was installed improperly or it was not installed, and
 - a self-locking nut that either was degraded or not torqued was used
- This allowed the nut to unthread and separate from the bolt.



NTSB Finding

“The mechanic, inspector, and check pilot each had at least one opportunity to observe the fore/aft servo self-locking nut and split pin; however, they did not note that the split pin was installed improperly or not present.”



Maintenance and Inspection Errors

- Improper securing of the fore/aft servo
- Improper tension of the hydraulic belt
- Incomplete maintenance inspection



Maintenance Personnel Fatigue

- The mechanic
 - Recent sleep and wake activity
 - Shift change
 - Inadequate sleep



Maintenance Personnel Fatigue

- The inspector
 - Recent sleep and wake activity
 - Shift change
 - Long duty day



Maintenance Personnel Fatigue

Personnel	Normal Shift	Shift Originally Scheduled for December 6	Actual Schedule on December 6
Mechanic	Noon to 11:00 pm	Off duty	5:50 am to 6:46 pm
Inspector	Noon to 11:00 pm	Off duty	5:31 am to 6:55 pm



Maintenance Personnel Fatigue

- Effects of fatigue
 - Difficulty sustaining attention
 - Memory errors
 - Lapses in performance



Fatigue Affects on Performance

- 2 hour sleep debt can produce performance decrements comparable to those produced by BAC of 0.045.
- 4 hour sleep debt can produce performance decrements comparable to BAC of 0.095.



Sleep loss decreases performance

- 2 hours sleep loss
 - » Productivity decreases by 17 percent
- 4 hours sleep loss
 - » Productivity decreases by 43 percent

- Source: Mark Rosekind, Ph.D.

According to experts...

“When you lose sleep or disrupt your sleep clock, every aspect of your capability as a human being is impaired.”

- Mark Rosekind, Ph.D.

Rosekind says that even moderate sleep loss can result in decreases in:

- » **Memory** (up to 20%)
- » **Vigilance** (75%)
- » **Communication skills** (30%)
- » **Reaction times** (25%)
- » **Judgment-making skills** (50%)

NTSB Finding

- “Because both the mechanic and the inspector had insufficient time to adjust to working an earlier shift than normal, they were experiencing fatigue during the December 6 shift.”
- “In addition, the mechanic had an inadequate amount of sleep and the inspector had a long duty day, both of which also contributed to the development of their fatigue.”



NTSB Finding

“Both the mechanic’s performance and the inspector’s performance probably were degraded by fatigue, which contributed to the improper securing of the fore/aft servo connection hardware, the improper installation of the hydraulic belt, and the incomplete maintenance inspection of the accident helicopter, respectively.”



Enhancing Crew Monitoring and Cross-checking





Japan Airlines Flight 123 crashed during landing at San Francisco International Airport in July, resulting in three deaths and injuring more than 200.

Pilots Cited in July Jet Crash

Confusion Surrounding Automation Linked to Landing Disaster in San Francisco

By Alex Posner

U.S. accident investigators

won't issue that the automation system was inadvertently shifted into an inactive mode before the crash.

Instead, Japan's administration declined to comment, saying, which provided evidence that the crew of the aircraft "777" at

one of an industry-government panel that issued a study last month spelling out the potential hazards of pilots who become so

Pilots said to err in properly monitoring speed and trajectory.

The NTSB is expected to answer the biggest puzzle surrounding the crash of Japan's

based on the details, the pilots didn't realize computerized speed controls had become inactive after they changed a setting to manual and closed back the

and others if an



NTSB

Asiana 214

“The flight crew did not adequately monitor airspeed between 500 and 200 ft.”



NTSB

Accident Summary

- February 16, 2005
- Pueblo, CO
- Cessna Citation 560
 - Owned by Circuit City, Operated by Martinair
- Eight fatalities
- Part 91 flight




Arrival into Pueblo Area

PUB Airport

0906:00
Runway Change


0911:48: Glideslope intercept,
full flaps extended



Data use subject to license.

© 2004 DeLorme. Topo USA® 5.0.

www.delorme.com



0912:37: I don't know if you want to run your ice a little bit. You got the Vref there.

0912:17: Just a brief on the missed approach, if we have to. It's climb to seven thousand, direct to Pueblo localizer.

All right.

0912:42 Upset

Uh, Pueblo outer marker.

Right turn or left turn.

It doesn't say. It says direct to it, uh ...

All right.

0912:31: Straight ahead on the other side.

Probable Cause

“Flight crew’s failure to effectively monitor and maintain airspeed and comply with procedures for deice boot activation on the approach, which caused an aerodynamic stall from which they did not recover.”



BARRIERS TO EFFECTIVE MONITORING



Underlying factors associated with poor monitoring

Effective monitoring is not easy and intuitive.

- It requires skill and discipline



Underlying factors associated with poor monitoring

There is somewhat of a monitoring paradox that works against effective monitoring.

- Serious errors do not occur frequently which can lead to boredom and complacency

"A low-probability, high-criticality error is exactly the one that must be caught and corrected."



Barriers to Effective Monitoring

- Distractions
- Automation reliance
- Fatigue
- High workload
- Complacency
- Runway/arrival change
- Rushing/time pressure



Barriers to Effective Monitoring

- Distractions
- Automation reliance
- Fatigue
- High workload
- Complacency
- Runway/arrival change
- Rushing/time pressure



Barriers to Effective Monitoring

- Looking without seeing
 - Inattention blindness
 - Change blindness
- Poor workload management/
task allocation



Change Blindness

- “People are surprisingly poor at detecting even gross changes in a visual stimulus if they occur in objects that are not the focus of attention.”

- S. Palmer, 1999, *Vision Science*.



NTSB

MACH

ALT CRZ

NAV

AP1
1FD2
A/THR



MACH

ALT CRZ

NAV

1FD2
A/THR



Inattention Blindness



WHAT YOU CAN DO TO IMPROVE MONITORING





NTSB



NTSB

Actively Monitor

- Pilots must “actively monitor” the aircraft.
- This means you must mentally fly the aircraft, even when the autopilot or other pilot is flying.
 - Monitor the flight instruments just as you would when hand flying.



Strategically Planning Workload

- In approximately one-third of the cases studied by researchers, pilots “failed to monitor errors, often because they had planned their own workload poorly and were doing something else at a critical time.”
 - Jentsch, Martin, Bowers (1997)
- Doing the right thing at the wrong time.
- Doing the wrong things at the wrong times.




Strategically Planning Tasks

- Pilots should recognize those flight phases where poor monitoring can be most problematic.
- Strategically plan workload / tasks to maximize monitoring during those Areas of Vulnerability (AOV)
 - Examples of non-monitoring tasks that should be conducted during lower AOV include stowing charts, programming the FMS, getting ATIS, accomplishing approach briefing, PA announcements, non-essential conversation, etc.




Areas of Vulnerability



NTSB

Areas of Vulnerability




Enhancing Monitoring: Taxi

- When approaching an active runway, **both pilots** will suspend non-monitoring tasks to ensure the hold short instructions are complied with.
- Non-monitoring tasks:
 - FMS programming
 - Calling FBO
 - Checklists
 - etc.



Enhancing Monitoring: In-Flight

- Perform non-essential duties/activities during lowest workload periods (e.g., cruise altitude or level flight)
- During the last 1000 feet of altitude change, both pilots will focus on making sure the aircraft levels at the assigned altitude



Approach Briefing: Before TOD



- By briefing prior to TOD, greater attention can be devoted to monitoring during descent.
- LOSA Data: Crews who briefed after TOD averaged making 1.6 times more errors in descent/ approach/ landing phase.



How is your monitoring?

- One way of assessing your current monitoring ability is to ask: “How often do I miss making the 1,000’ to level-off altitude callout?”
 - When this callout is missed, you probably aren’t actively monitoring the aircraft.



Paradigm shift



It must become accepted that monitoring is a “core skill,” just as it is currently accepted that a good pilot must possess good “stick and rudder” and effective communicational skills.



Summary

- Inadequate flight crew monitoring has been cited by a number of sources as a problem for aviation safety.
- While it is true that humans are not naturally good monitors, crew monitoring performance can be significantly improved.



**“If I had been watching the instruments,
I could have prevented the accident.”**

- First Officer in fatal CFIT accident



12 20'99



National Transportation Safety Board